

**SECRET**

IDEA-0899

Copy 5 of 5

24 September 1962

MEMORANDUM FOR: Deputy Assistant Director, OSA-DD/R

SUBJECT : DC Generator Failures on U-2 Aircraft

DC Generators are standard Air Force equipment and are obtained by the [ ] from normal Air Force supply channels. As a result of [ ] complaint in [ ] 092 (attached) we have consulted with [ ] and [ ] and have requested the following actions:

- 25X1A a. [ ] to perform teardown inspection on the two faulty generators and submit findings and recommendations to this Headquarters.
- 25X1A b. [ ] to report apparent poor quality control to the prime USAF depot concerned and request corrective action.
- 25X1A c. [ ] to institute new SOP whereby LAC will pre-inspect all DC generators prior to issue.
- 25X1A d. [ ] to send all reparable DC generators to LAC for repair unless adequate quality control from prime USAF depot can be assured.

[ ]  
Chief, Materiel Division  
OSA-DD/R

25X1A

[ ] are  
Dist: Cy 1 - Addressee  
2 - AD/OSA  
3 - OD/OSA  
4 - MD/OSA  
5 - [ ]

NOT TO BE DISSEMINATED  
OUTSIDE OSA-DD/R

**SECRET**